Main Library Facility Planning

Facilities Planning Committee
October 24, 2012

OPL Board Strategic Plan 2012-2015

Strategic Priority B

Places and Spaces that are Vital, Welcoming Community Hubs

Main Library



Main Library – Current State

- Opened in 1974 built for books
- Largest (90,418 sq ft) and busiest OPL branch
- Has never had a comprehensive renovation
- Accessibility issues
- Lack of public meeting and gathering spaces
- Not built for modern library service delivery especially technology

Main Library Survey

- Opinion survey of users/non-users undertaken by Nanos Research in spring 2012
- Main Library is branch for the downtown community
- Users like the central downtown location and wide selection of resources
- 83% of users highly satisfied but...
 - People want more resources and a refreshed library

Board Direction (1)

May 14, 2012 motion approved:

 That the Board approve the following branches as facilities renewal priorities for future planning including incorporation into the nine-year capital forecast: Main, Rosemount, Constance Bay, Centennial, Emerald Plaza, Elmvale Acres, North Gower and Orléans.

Board Direction (2)

September 10, 2012 motion approved:

- That the Board receive the Main Library Building Condition Audit and Structural Assessment (Morrison-Hershfield Report No. 2123051.00 July 24, 2012) report; and
- That the report be referred to the Facilities Planning Committee for consideration; and
- That staff bring a report to the Board in November 2012 on recommended next steps in planning for renewal of the existing Main Library facility.

Building Condition Audit Key Results (1)

- Main Library building is in generally good condition
- About \$6.3 million identified in repairs/replacements over next 10 years
 - \$4.2 million to replace 40 year old electrical system (end of life)
 - \$1.1 million for parking garage repairs
 - \$1.0 million for other repairs/replacements

Building Condition Audit Key Results (2)

Functionality

- Large open spaces on the 1st 3rd floors offer flexibility other than the walls surrounding the elevators, stairwells and atrium
- The basement level has limited flexibility to be altered

Building Condition Audit Key Results (3)

- Expansion Potential
 - Limited expansion potential
 - Challenging significant structural and legal encumbrances
 - Maximum potential is for 2 storey addition of 8,800 square feet
 - Any addition would impact on air rights and the Sir Richard Scott building

Moving Forward

Guiding Principles

Fiscally responsible plan that:

- Supports modern library service delivery and
- Includes a significant fund-raising component

Planning Options

 Three options to consider in Main Library facility planning next steps:

Option 1: Maintain

Option 2: Modernize

Option 3: Expand

Option 1: Maintain

Description	Status quo			
Scope	Life cycle maintenance of Main Library facility			
Order of Magnitude	\$			
Results	 Responds to condition audit but does not address current facility limitations in supporting library service delivery Restricts RFID implementation Facility is not refreshed 			
Duration	Short-term solution (10 years)			
Strategic Alignment	 Council-approved Comprehensive Asset Management strategy B: Places and Spaces that are Vital, Welcoming Hubs →Maintenance of current facilities 			

Option 2: Modernize

Description	Modernizing of current Main Library through redesign and refreshing of current space			
Scope	Life cycle maintenance of facility Major renewal and comprehensive renovation of existing facility maximizing public space			
Order of Magnitude	\$\$			
Results	 Responds to condition audit Addresses service delivery deficiencies and accessibility issues Will support modern library service delivery (open spaces, more people places, technology friendly) Allows for optimal RFID implementation through facility design integration 			
Duration	Mid-term solution (20 years)			
Strategic Alignment	 ◆A: Services that are Relevant, Accessible and Customer-Centric ◆B: Places and Spaces that are Vital, Welcoming Hubs →Maintenance and renewal of current facilities →Sustainability 			

Option 3: Expand

Description	Expansion and major renovation of current Main Library				
Scope	Total renewal and renovation of existing space Expansion through two storey addition to 4 th and 5 th floors				
Order of Magnitude	\$\$\$				
Results	 Will address issues raised in condition audit Major renovation with building stripped back to its shell Increased service delivery space (+9.7%) Addresses service delivery deficiencies and accessibility issues Will support modern library service delivery (open spaces, more people places, technology friendly) Allows for optimal RFID implementation through facility design integration 				
Duration	Long-term solution (>20 years)				
Strategic Alignment	 Council-approved Comprehensive Asset Management strategy A: Services that are Relevant, Accessible and Customer-Centric B: Places and Spaces that are Vital, Welcoming Hubs →Maintenance and renewal of current facilities →Building new spaces →Sustainability 				

Comparison of Options

Results in a facility that	Option 1: Maintain	Option 2: Modernize	Option 3: Expand
Is structurally sound	X	X	X
Meets functional program requirements		Χ	Χ
Is accessible		X	X
Better supports technology-based services to customers		X	X
Supports full implementation of RFID technology		X	X
Is a vital, welcoming community hub		X	X
Maximizes public spaces		X	X
Offers increased square footage			X

Preferred Option

- Staff recommend Option 2: Modernize as the preferred option
- Rationale
 - Modest renewal of the existing facility
 - Moderately priced
 - Supports delivery of modern library service

Recommendations (1)

- 1. That the Facilities Planning Committee approve the following motion:
 - That Option 2: Modernize be the recommended option in planning for renewal of the existing Main Library facility

Recommendations (2)

- 2. That the recommended option be presented through a staff report at the November 19, 2012 Board meeting
- 3. That the funding for the planning next steps be identified as the Jan Harder Capital Trust Fund.

Planning Next Steps - 2013

- Program requirements: Engagement of external services to identify functional requirements
- 2. <u>Design vision</u>: Engagement of architectural services to undertake preliminary feasibility analysis including order of magnitude costs